





The plug has to be connected to terminal CN10.



Jumper JP2 must be removed.



Remove protective foil of self adhesive fixing socket and stick it on the interior housing of the unit. In case of a further replacement of the battery it is only necessary to replace the previous replacement battery.