

BPT 320 KB/R - Identification of correct electrical spare parts

- 1 320 KB with bottom plate made from steel resp. round cover of power connector



Due to their age it is often impossible to seal them correctly. Therefore we do not offer spare parts any more. The focus is on preventing personal injuries. Whenever needed a defective unit can be returned to our factory to proof whether a repair is possible or not.

- 2 320 KB/R with injection molded bottom plate with injection point in the middle (colours blue and grey)



Available repair kits

BPT 320 KB:



- 139788 repair kit BPT 320 KB panel and controller
- 118735 repair kit BPT KB panel
- 107023 repair kit BPT 320 KB/AS silicon heater up to 12/2011
- 118912 repair set BPT 320 KB/KBR bottom plate and gasket up tp 12/2011

320 KBR:



- 128646 repair kit BPT 320 KBR panel and controller up to 12/2011
- 118736 repair kit BPT KBR panel
- 107024 repair kit BPT 320 KBR/AS silicon heater up to 12/2011 *)
- 118912 repair set BPT 320 KB/KBR bottom plate and gasket up tp 12/2011

*) no longer available

3 320 KB/R with machined plastic bottom plate (colour grey)



Available repair kits

BPT 320 KB:



- 139788 repair kit BPT 320 KB panel and controller
- 118735 repair kit BPT KB panel
- 120010 repair kit BPT 320 KB/AS silicon heater from 01/2012
- 120009 repair set BPT 320 KB/KBR bottom plate and gasket from 01/2012 *)

320 KBR:



- 119916 repair kit BPT 320 KBR panel and controller from 01/2012 *)
- 118736 repair kit BPT KBR panel
- 119917 repair kit BPT 320 KBR/AS silicon heater from 01/2012
- 120009 repair set BPT 320 KB/KBR bottom plate and gasket from 01/2012 *)

*) no longer available